FIG. 1A




FIG. 1B





FIG. 1C

V-Grouve Bent Relaxation Jacket Portion

Bare Fiber Portion Ribbon Fiber Portion (Jacket Portion)






FIG. 3

FIG. 4A




FIG. 4B

Ideal Position (U,U)

(0,0)

